

Volta

Manager Desk

MW-DT-N-473-475



Installation instruction


Web: www.mwworkstation.com

Tel: +86 13695211636

Mail: robbor@mwworkstation.com

Manager Desk


PRODUCT



Manager Desk


PARTS SHOW

A




[Supervisor desk cabinet]

B




[Countertop]

C




[Two-way die-casting connector]

D




[Cold rolled steel pipe]

E



[End foot assembly]

F




[F]
Adjustment
foot joint



[G]
Adjusting
feet



[I]
M6*16 cylindrical
head screw



[H]
Besimple Adjustable
Feet




[J]
ST4*16
self-tapping screw

[small parts]


INSTALLATION STEPS

1




Hx8

H




Ax1

2




Ax1



Cx4 Dx2 Ex1 Fx2 Gx2 Ix4

3



Ax1 Bx1 Dx2 Ex1 Jx8

